





FIG. 1




*FIG. 2*



3 / 15

FIG. 3





4 / 15

FIG. 4




FIG. 5




FIG. 6

1	0	1	0	1	0	1	0	1	0
1	0	1	0	1	0	1	0	1	0

FIG. 7

1	0	1	0	1	0	1	0	1	0
1	0	1	0	1	0	1	0	1	0
1	0	1	0	1	0	1	0	1	0

FIG. 8

1	0	1
0	1	0
1	0	1


FIG. 9

0	1	0
1	0	1
0	1	0






FIG. 10







7 / 15

FIG. 11



*FIG. 12*

*FIG. 13*






**FIG. 14****FIG. 15**

FIG. 16*FIG. 17**FIG. 18*

*FIG. 19*

1	2	3	4
5	6	7	8
9	10	11	12
13	14	15	16

FIG. 20


1	4	5	8
3	2	6	7
9	10	13	15
11	12	14	16

*FIG. 21*

1
2
3
4
5
6
7
8
9
10
11
12

FIG. 22

1
3
2
4
5
7
6
8
10
9
11
12

*FIG. 23*

*FIG. 24*